

Figure 1
(Prior Art)




Figure 2




Figure 3A




Figure 3B




Figure 4A

R07720 "9EE8E0660




Figure 4B

CLIENT DHCP LEASE NEGOTIATIONS
404




Figure 5A




Figure 5B




Figure 6A




Figure 6B




Figure 6C




Figure 7A




Figure 7B




Figure 7C

INTERNAL PHONE to INTERNAL PHONE RTP FLOW


490A

Figure 8A




Figure 8B

TORTOISE EXECUTION




Figure 8C

PHONE to MEDIA GATEWAY RTP FLOW
490B




Figure 9A




Figure 9B




Figure 9C



PHONE to EXTERNAL PHONE RTP FLOW
490C




Figure 10A

卷之三




Figure 10B




Figure 11